

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	838	((On or Off) near2 switch\$3) and (airbag or "restraint device" or seatbelt) and sensor\$1 and control\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 08:46
S2	196	S1 and @py<"2002"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 09:25
S3	0	vehicle and (airbag or seatbelt or "restraint device") and (transistor with sqib) and switch\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 09:26
S4	84	vehicle and (airbag or seatbelt or "restraint device") and (transistor with squib) and switch\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 09:56
S5	10	("4222030" "4287431" "4868817" "4950914" "5038134" "5045835" "5083276" "5182459" "5331211" "5351185").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2007/10/30 09:37
S6	4	("4975850" "5181011" "5182459" "5286053").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2007/10/30 09:42
S7	42	vehicle and (airbag or seatbelt or "restraint device") and transistor and switch\$3 and ((check\$3 or diagnos \$3 or monitor\$3) with (malfunction or erroneous\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 10:07
S8	194	vehicle and (airbag or seatbelt or "restraint device") and ((check\$3 or diagnos\$3 or monitor\$3) with (malfunction or erroneous\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 10:20

S9	69	S8 and @py<"2003"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 10:11
S10	215	vehicle and (airbag or seatbelt or "restraint device") and (airbag with (malfunction or erroneous\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 13:20
S11	43	S10 and (switch\$3 with (ON or OFF))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 10:33
S12	2	("5939976").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/30 10:49
S13	356	(erroneous near2 triggering)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 13:14
S14	7	(check\$3 with (erroneous near2 triggering))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 13:16
S15	50	(detect\$3 with (erroneous near2 triggering))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 13:16
S16	90	vehicle and (airbag or seatbelt or "restraint device") and (malfunction or erroneous\$2) and ((activation or deactivation) near3 switch\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 13:21
S17	12	ringger-klaus.in.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:07

S18	12	schou-frank.in.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:10
S19	1924	B60R21/16.IPC. OR G08G1/01.IPC.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:10
S20	18	S19 and (switch near4 position\$1) and (processor or module or logic)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:12
S21	15	("20020074781" "20050151354" "20050230943" "20060208470" "5686559" "5738369" "5882032" "6029992" "6119545" "6676155" "6682092" "6830263" "6846995" "7052035" "7121581").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/10/01 10:12
S22	64621	(switch near4 position \$1) and (processor or module or logic)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:15
S23	347	(180/271, "282".ccls. or 701/45 or 280/734, "735".ccls. or 340/933) and (switch near4 position\$1) and (processor or module or logic)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:15
S24	108	("3275975" "3974350" "4198864" "4284863" "4329549" "4573706" "4683373" "4732157" "4900880" "4933515" "4984651" "4995639" "5071160" "5074583" "5101831" "5118134" "5161820" "5184845" "5187657"	US-PGPUB; USPAT; USOCR	OR	ON	2008/10/01 10:20

"5202831"		"5222761"
	"5232243"	
"5322323"		"5330226"
	"5366241"	
"5398185"		"5413378"
	"5439249"	
"5446661"		"5448996"
	"5454591"	
"5474327"		"5479932"
	"5482314"	
"5484166"		"5515933"
	"5525843"	
"5528698"		"5540461"
	"5549323"	
"5573269"		"5602734"
	"5605348"	
"5622178"		"5624132"
	"5636864"	
"5653462"		"5670853"
	"5671733"	
"5683103"		"5691693"
	"5699057"	
"5722686"		"5732375"
	"5748473"	
"5758899"		"5770997"
	"5782485"	
"5783871"		"5785347"
	"5790031"	
"5802479"		"5829782"
	"5844486"	
"5846206"		"5848802"
	"5851026"	
"5865463"		"5885129"
	"5889870"	
"5890085"		"5900677"
	"5901978"	
"5906393"		"5935182"
	"5943295"	
"5947514"		"5948031"
	"5954360"	
"5964478"		"5964815"
	"5967549"	
"5997033"		"6007095"
	"6010151"	
"6014602"		"6016351"
	"6018693"	
"6020812"		"6025783"
	"6026340"	
"6027138"		"6029105"
	"6039139"	
"6043736"		"6053529"
	"6095553"	
"6095554"		"6113137"
	"6123357"	
"6199902"		"6208249"

		"6220627" "6255939" "6474683" "6513833" "RE37260").PN.				
S25	7	("4243248" "5176214" "5657831" "5796177" "5957490" "6072246" "6363307").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/10/01 10:22
S26	2530	180/271	US-PGPUB; USPAT; USOCR	OR	ON	2008/10/01 10:24
S27	3958	280/735	US-PGPUB; USPAT; USOCR	OR	ON	2008/10/01 10:26
S28	1800	340/933	US-PGPUB; USPAT; USOCR	OR	ON	2008/10/01 10:26
S29	2256	((switch near4 position \$1) and (processor or module or logic)).ab.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:30
S30	4	(switch near4 position \$1).ab. and (verif\$6 with (processor or module or logic)).ab.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:35
S31	4434	(verif\$6 with (processor or module or logic)).ab.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:36
S32	18	S31 and (vehicle or car or automobile) and (safety or restraint) and protect\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:36
S33	2	("5513878").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/10/01 10:38
S34	4	("4975850" "5181011" "5182459" "5286053").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/10/01 10:44
S35	2703	(switch with position) and erroneous and (processor or computer) and logic	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:48

S36	879	S35 and verif\$6	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/10/01 10:49
-----	-----	------------------	---	----	----	---------------------

10/1/08 11:27:02 AM

C:\Documents and Settings\TTo1\My Documents\TextSearchWorkspace\10520973c.wsp